



*Solving environment-related business problems worldwide*

[www.deltaenv.com](http://www.deltaenv.com)

27141 Aliso Creek Road • Suite 270

Aliso Viejo, California 92656 USA

949.362.3077 800.477.7411

Fax 949.362.0290

April 13, 2006

Mr. Patrick Lei  
Los Angeles County Department of  
Public Works  
900 South Fremont Avenue  
Alhambra, California 91803

Sent by FedEx

Subject: Quarterly Site Status Report Submittal

Dear Mr. Lei:

On behalf of Atlantic Richfield Company, Delta Environmental Consultants, Inc. is submitting the enclosed Quarterly Site Status Report for the First Quarter 2006. The enclosed quarterly report was prepared for the following ARCO Facility:

**ARCO Facility No.**

1592

**LADPW Site No.**

EP-1 011979-037116


**Location**

5 West Foothill Blvd, Arcadia

If you have any questions or comments concerning this correspondence, please contact John Batchelder at (714) 670-3061.

Sincerely,

**DELTA ENVIRONMENTAL CONSULTANTS, INC.**

  
\_\_\_\_\_  
Amy R. Mora  
Project Manager

4/13/06  
Date

Enclosure: Atlantic Richfield Company Quarterly Site Status Report

cc: Mr. John Batchelder, Atlantic Richfield Company, La Palma, California  
Mr. Cleve Solomon, SECOR International, Inc. Thousand Oaks, California  
Mr. John Nahas, 5 West Foothill Boulevard, Arcadia, California

**ATLANTIC RICHFIELD COMPANY QUARTERLY SITE STATUS REPORT  
FIRST QUARTER 2006  
APRIL 15, 2006**

ARCO Facility No.: 1592 Address: 5 West Foothill Boulevard, Arcadia, California  
Atlantic Richfield Co. Env. Manager / Phone No.: Mr. John Batchelder / (714) 670-3061  
Consulting Co. / Contact Person / Phone No.: SECOR International Incorporated / Dr. G. Cleve Solomon /  
(805) 230-1266  
Primary Agency / Contact Person / Regulatory ID No.: County of Los Angeles Department of Public works (LADPW) /  
Mr. Patrick Lei / EP-1 011979-037116

**WORK PERFORMED THIS QUARTER (First – 2006):**

1. Submitted the *Quarterly Site Status Report* to the LADPW with request for No Further Action status and case closure.

**WORK PROPOSED FOR THE NEXT QUARTER (Second – 2006):**

1. Submit *Quarterly Site Status Report*.

Current Phase of Project: Assessment/Closure  
Depth to Groundwater: 200+ feet Measured      Estimated X  
Groundwater Gradient: Unknown (Magnitude) Unknown (Direction)


**ATTACHMENTS:** Site Location Map (Figure 1)  
Site Map (Figure 2)

**DISCUSSION:**


The hydrocarbon-impacted soil at the site has been sufficiently assessed vertically and horizontally. Therefore, on behalf of Atlantic Richfield Company, Delta requests that no further actions be required of Atlantic Richfield Company for this site.

If you have any questions or comments concerning this correspondence, please contact John Batchelder at (714) 670-3061.

**DELTA ENVIRONMENTAL CONSULTANTS, INC.**

  
Amy Mora  
Project Manager

4/13/06  
Date



GENERAL NOTES:  
 BASE MAP FROM 3-D TOPO QUADS  
 MT. WILSON, CA. QUADRANGLE  
 7.5 MINUTE TOPOGRAPHIC MAP  
 1966  
 PHOTOREVISED 1988



QUADRANGLE LOCATION





FIGURE 1


SITE LOCATION MAP  
 ARCO FACILITY NO. 1592  
 5 W. FOOTHILL BOULEVARD  
 ARCADIA, CA.

PROJECT NO. AM03-169	DRAWN BY
FILE NO. A3-808-03	PREPARED BY A. BAIRD
DATE 09 DEC 03	REV. 0 REVIEWED BY





### LEGEND

- B-1 ● SOIL VAPOR EXTRACTION WELL LOCATION
- B-2 • SOIL BORING LOCATION
- T5A ▼ TANK SOIL SAMPLE LOCATION
- D4A ▼ DISPENSER SOIL SAMPLE LOCATION
-  APPROXIMATE LIMIT OF OVEREXCAVATION




FIGURE 2

SITE MAP  
ARCO FACILITY NO. 1592  
5 WEST FOOTHILL BOULEVARD  
ARCADIA, CA.

PROJECT NO.  
AM03-169

FILE NO.  
A3-169-01

DATE  
17 MAR 04

DRAWN BY  
K. MARTIN

PREPARED BY  
A. BAIRD

REVIEWED BY

